



Wiring Diagram for 1A3-4 TSU Sending Unit




Connector pin out

<u>Old Connector</u>		<u>New Connector</u>
Pin A&B	Ground (black wire)	Pin 2
Pin H	(+8) volts from Tachometer (Red wire)	Pin 1
Pin D	TSU output (White Wire)	Pin 3



Pin out, viewed from solder end of plug



Pin out, viewed from solder end of panel mount socket